



254963

Field Report  
Wilhelm Properties  
New Carlisle/Clark Co. (SWDO)  
3/29/90  
Palmer

Bill Palmer collected soil samples from under each trailer on Arnold Wilhelm's properties. The samples were collected where leaks were observed in the trailers.

Sample Descriptions

- #1 Trailer on 1761 Liberty Road. Soil sample collected under leak in trailer. Palmer collected visually-contaminated soil by using a stainless steel scoop, mixing soil in a stainless steel bowl, and scooping into a 1-quart jar. Discolored soil. Looks like an oil-like material. Collected at 1000hr.
- #2 Trailer on 8081 Lower Valley Pike. Soil sample collected under leak in trailer. Palmer collected visually contaminated soil by using a stainless steel scoop, mixing soil in a stainless steel bowl, and scooping into a 1-quart jar. Dark colored soil, crusty on surface. Collected at 1020hr.
- #3 Trailer on 8081 Lower Valley Pike. Soil sample collected under leak in trailer. Black tar-like substance leaking out back of trailer. Palmer collected visually-contaminated soil by using a stainless steel scoop, mixing soil in a stainless steel bowl and scooping into a 1 pint jar. Collected at 1030hr.